L Number	Hits	Search Text	DB	Time stamp
-	1	((measur$5 or detect$3 or sens$3) near3 (position or location)) and (pointing adj error) and ((geometric or geometrical) adj error adj vector)	USPAT; US-PGPUB	2004/10/20 06:58
-	1	(pointing adj error) and ((geometric or geometrical) adj error adj vector)	USPAT; US-PGPUB	2004/10/19 10:20
-	1	((geometric or geometrical) adj error adj vector)	USPAT; US-PGPUB	2004/10/19 10:24
-	789	pointing adj error	USPAT; US-PGPUB	2004/10/19 14:24
-	283	((measur$5 or detect$3 or sens$3) near3 (position or location)) and (pointing adj error)	USPAT; US-PGPUB	2004/10/19 10:21
-	2	((measur$5 or detect$3 or sens$3) near3 (shaft or spindle or axle) near3 (position or location)) and (pointing adj error)	USPAT; US-PGPUB	2004/10/19 10:23
-	1	((measur$5 or detect$3 or sens$3) near3 (shaft or spindle or axle) near3 (position or location)) and (determin$5 near3 error near3 vector) and (pointing adj error)	USPAT; US-PGPUB	2004/10/19 10:23
-	8	(geo$9 near3 (error adj vector))	USPAT; US-PGPUB	2004/10/19 10:26
-	1	((shaft or spindle or axle or axis or rotator or rotor) near3 (distance or range) near3 (measur$5 or detect$3 or sens$3) near3 (probe or sensor or tranducer or detector)) and ((measur$5 or detect$3 or sens$3) near3 (shaft or spindle or axle or axis or rotator or rotor) near3 (position or location or rotation or angle or turn)) and (determin$5 near3 geo$9 near3 (error or fault) near3 vector) and (determin$5 near3 (pointing or indicat$3) near3 (error or fault))	USPAT; US-PGPUB	2004/10/19 10:42
-	1	((shaft or spindle or axle or axis or rotator or rotor) near3 (distance or range) near3 (measur$5 or detect$3 or sens$3) near3 (probe or sensor or tranducer or detector)) and ((measur$5 or detect$3 or sens$3) near3 (shaft or spindle or axle or axis or rotator or rotor) near3 (position or location or rotation or angle or turn)) and (determin$5 near3 (error or fault) near3 vector) and (determin$5 near3 (pointing or indicat$3) near3 (error or fault))	USPAT; US-PGPUB	2004/10/19 10:43
-	3	((shaft or spindle or axle or axis or rotator or rotor) near3 (distance or range) near3 (measur$5 or detect$3 or sens$3) near3 (probe or sensor or tranducer or detector)) and ((measur$5 or detect$3 or sens$3) near3 (shaft or spindle or axle or axis or rotator or rotor) near3 (position or location or rotation or angle or turn)) and (determin$5 near3 (pointing or indicat$3) near3 (error or fault))	USPAT; US-PGPUB	2004/10/20 08:10
-	189	73/1.01.ccls.	USPAT; US-PGPUB	2004/10/19 10:44
-	0	73/175.ccls.	USPAT; US-PGPUB	2004/10/19 10:44
-	0	73/177.ccls.	USPAT; US-PGPUB	2004/10/19 10:44
-	0	73/178.ccls.	USPAT; US-PGPUB	2004/10/19 10:44
-	154	73/179.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
-	619	73/865.9.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
-	632	73/866.5.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
-	216	73/432.1.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
-	1284	701/1.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
-	1104	701/200.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
-	1114	701/207.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
-	445	701/214.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
-	145	701/221.ccls.	USPAT; US-PGPUB	2004/10/19 10:46

-	407	702/85.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	308	702/94.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	190	702/95.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	254	702/127.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	646	702/150.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	253	702/151.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	211	702/152.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	173	702/153.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	53	714/699.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	178	714/703.ccls.	USPAT; US-PGPUB	2004/10/19 10:47
-	0	702/94.ccls. and 73/1.77.ccls.	USPAT; US-PGPUB	2004/10/19 10:48
-	0	702/94.ccls. and 73/432.1.ccls.	USPAT; US-PGPUB	2004/10/19 10:48
-	0	702/94.ccls. and 701/1.ccls.	USPAT; US-PGPUB	2004/10/19 10:48
-	0	702/94.ccls. and 714/699.ccls.	USPAT; US-PGPUB	2004/10/19 10:49
-	0	702/94.ccls. and 714/703.ccls.	USPAT; US-PGPUB	2004/10/19 10:49
-	1	702/94.ccls. and 73/1.01.ccls.	USPAT; US-PGPUB	2004/10/19 10:50
-	2	702/94.ccls. and 73/1.75.ccls.	USPAT; US-PGPUB	2004/10/19 10:51
-	1	702/94.ccls. and 73/1.78.ccls.	USPAT; US-PGPUB	2004/10/19 10:52
-	10	702/94.ccls. and 73/1.79.ccls.	USPAT; US-PGPUB	2004/10/19 10:52
-	3	702/94.ccls. and 73/865.9.ccls.	USPAT; US-PGPUB	2004/10/19 10:57
-	1	702/94.ccls. and 73/866.5.ccls.	USPAT; US-PGPUB	2004/10/19 10:57
-	4	702/94.ccls. and 701/200.ccls.	USPAT; US-PGPUB	2004/10/19 10:57
-	10	702/94.ccls. and 701/207.ccls.	USPAT; US-PGPUB	2004/10/19 10:58
-	2	702/94.ccls. and 701/214.ccls.	USPAT; US-PGPUB	2004/10/19 10:58
-	6	702/94.ccls. and 701/221.ccls.	USPAT; US-PGPUB	2004/10/19 10:58
-	14	702/94.ccls. and 702/85.ccls.	USPAT; US-PGPUB	2004/10/19 10:59
-	41	702/94.ccls. and 702/95.ccls.	USPAT; US-PGPUB	2004/10/19 11:00
-	4	702/94.ccls. and 702/127.ccls.	USPAT; US-PGPUB	2004/10/19 11:02
-	51	702/94.ccls. and 702/150.ccls.	USPAT; US-PGPUB	2004/10/19 11:03
-	20	702/94.ccls. and 702/151.ccls.	USPAT; US-PGPUB	2004/10/19 11:06
-	8	702/94.ccls. and 702/152.ccls.	USPAT; US-PGPUB	2004/10/19 11:07
-	7	702/94.ccls. and 702/153.ccls.	USPAT; US-PGPUB	2004/10/19 11:07
-	490	((pointing or indicat$3) adj (error or fault)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (shaft or spindle or axle or axis) near5 (position or location))	USPAT; US-PGPUB	2004/10/19 14:30

-	1	((pointing or indicat$3) adj (error or fault)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (shaft or spindle or axle or axis) near5 (position or location)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (geo$9 adj (error or fault) adj vector))	USPAT; US-PGPUB	2004/10/19 14:30
-	1	((pointing or indicat$3) adj (error or fault)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (shaft or spindle or axle or axis) near5 (position or location)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (geo$9 adj (error or fault) adj vector))	EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:32
-	8	((pointing or indicat$3) adj (error or fault)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (shaft or spindle or axle or axis) near5 (position or location))	EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:30
-	0	((pointing or indicat$3) adj (error or fault)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (bearing) near5 (position or location)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (geo$9 adj (error or fault) adj vector))	EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:33
-	0	((pointing or indicat$3) adj (error or fault)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (bearing) near5 (position or location)) and ((determin$5 or measur$5 or detect$3 or sens$3) near5 (geo$9 adj (error or fault) adj vector))	USPAT; US-PGPUB	2004/10/19 14:33
-	704733	((method$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat$5 adj (distance or range)) with (measur$5 or determin$5 or detect$3 or sens$3) with (probe or transducer or detector or sensor)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:37
-	20434	((method$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat$5 adj (distance or range)) with (measur$5 or determin$5 or detect$3 or sens$3) with (probe or transducer or detector or sensor))) and ((measur$5 or determin$5 or detect$3 or sens$3) with (shaft or spindle or axle or axis) with (position or location))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:38
-	1091	((method$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat$5 adj (distance or range)) with (measur$5 or determin$5 or detect$3 or sens$3) with (probe or transducer or detector or sensor))) and ((measur$5 or determin$5 or detect$3 or sens$3) with (shaft or spindle or axle or axis) with (position or location)) and ((measur$5 or determin$5 or detect$3 or sens$3) with (pointing or indicat$3) with (error or fault))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:40
-	5	((method$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat$5 adj (distance or range)) with (measur$5 or determin$5 or detect$3 or sens$3) with (probe or transducer or detector or sensor))) and ((measur$5 or determin$5 or detect$3 or sens$3) with (shaft or spindle or axle or axis) with (position or location)) and ((measur$5 or determin$5 or detect$3 or sens$3) with geo$9 with error with vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:43
-	3	((method$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat$5 adj (distance or range)) with (measur$5 or determin$5 or detect$3 or sens$3) with (probe or transducer or detector or sensor))) and ((measur$5 or determin$5 or detect$3 or sens$3) with (shaft or spindle or axle or axis) with (position or location)) and ((measur$5 or determin$5 or detect$3 or sens$3) with geo$9 with error with vector) and ((measur$5 or determin$5 or detect$3 or sens$3) with (pointing or indicat$3) with (error or fault))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:41
-	8	((measur$5 or determin$5 or detect$3 or sens$3) with geo$9 with (error or fault) with vector) and ((measur$5 or determin$5 or detect$3 or sens$3) with (pointing or indicat$3) with (error or fault))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:44

-	61	((measur$5 or determin$5 or detect$3 or sens$3) with geo$9 with error with vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:54
-	4078	((measur$5 or determin$5 or detect$3 or sens$3) with (shaft or spindle or axle or axis) with (position or location or rotation) with error)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:56
-	904	((measur$5 or determin$5 or detect$3 or sens$3) near5 (shaft or spindle or axle or axis) near5 (position or location or rotation) near5 error)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:56
-	97	((measur$5 or determin$5 or detect$3 or sens$3) near5 (shaft or spindle or axle or axis) near5 (position or location or rotation) near5 (error or fault)) and ((pointing or indicating or indication or index or arrow or needle) near5 (error or fault))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 08:05
-	2	((measur$5 or detect$3 or sens$3 or determin$5) near3 (position or location or distance) near3 (shaft or spindle or axle or axis) near3 (end or limit)) and ((pointing or indicat$3 or index$3) adj error) and ((geometric or geometrical) adj error adj vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 07:01
-	2	((measur$5 or detect$3 or sens$3 or determin$5) near3 (position or location or distance) near3 (shaft or spindle or axle or axis) near3 (end or limit)) and ((pointing or indicat$3 or index$3) adj error) and (error adj vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 07:02
-	5	((measur$5 or detect$3 or sens$3 or determin$5) near5 (position or location or distance) near5 (shaft or spindle or axle or axis) near5 (end or limit)) and ((pointing or indicat$3 or index$3) near3 error) and (error near3 vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 07:03
-	77	((measur$5 or detect$3 or sens$3 or determin$5) near5 (position or location or distance) near5 (shaft or spindle or axle or axis)) and ((pointing or indicat$3 or index$3) near3 error) and (error near3 vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 07:08
-	1	((measur$5 or detect$3 or sens$3 or determin$5) near5 (position or location or distance) near5 (shaft or spindle or axle or axis)) and ((bearing or (roller adj bearing)) near5 error near5 vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 07:10
-	2	((measur$5 or detect$3 or sens$3 or determin$5) near5 (position or location or distance) near5 (shaft or spindle or axle or axis)) and ((bearing or (roller adj bearing)) with error with vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 07:33
-	2	((measur$5 or detect$3 or sens$3 or determin$5) near5 (shaft or spindle or axle or axis) with (geometric or geometrical or geometry) with error with vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 07:34
-	4	((measur$5 or detect$3 or sens$3 or determin$5) near5 (shaft or spindle or axle or axis) with (pointing or indicating or indication) with error with vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 07:35
-	97	((measur$5 or determin$5 or detect$3 or sens$3) near5 (shaft or spindle or axle or axis) near5 (position or location or rotation) near5 (error or fault)) and ((pointing or indicating or indication or index or arrow or needle) near5 (error or fault))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/20 08:06
-	1	4894788.pn.	USPAT	2004/10/20 08:10